All A/C units powered through a receptacle are to be inspected for receptacle damage due to over draw by the appliance. If damage is noted, appliance will be taken off-line until the circuit branch is upgrade or the appliance is identified as defective.

15 10:31 AM


Identified a potential fire risk for all camps
using 36 and 40 watt florescent fixtures,
both single and double tube devices.
VS VOSSLOH SCHWABE
L36. 334
230V~50Hz
13 12:52 PM

Ballasts burnt to noted overheating (identified by brown marks) ballasts of the same size/manufacturer